CoreDraw plug-in installation

1. copy folder "AM.CO.ZA_CDR" to c:\ (important : not rename this folder)

2. copy file "AM.CO.ZA_USB.gms" to CoreDraw install folder "C:\Program Files (x86)\Corel\CorelDRAW Graphics Suite X6\Draw\GMS"

3 .Open CorelDRAW then click' Tools' "**Customization…**" ->



Then click "**Commands**"-> "**Macros**" -> "AM_CO_AM. AM_CO_AM" as follows



it will display the following dialog box, click “**Appearance**”>“Import”>“Files”



it will display the following windows, then double click ”



am.co.za.ico”

Press the left mouse button and drag ”cutterpro.cutterpor”



to the toolbar

Click “**OK**”

How to use:

Output the Designed file then click



“Plotter Origin” select “Bottom left”

“Plotter units:” select “1016”



Click “**OK**”



Select the port connected to the plotter and start.