



CoreDraw plug-in installation

1. copy folder "AM.CO.ZA_CDR" to c:\ (important : not rename this folder)
2. copy file "AM.CO.ZA_USB.gms" to CoreDraw install folder "C:\Program Files (x86)\Corel\CorelDRAW Graphics Suite X6\Draw\GMS"


3. Open CorelDRAW then click 'Tools' "**Customization...**" ->




Then click "**Commands**" -> "**Macros**" -> "AM_CO_AM.
AM_CO_AM" as follows



it will display the following dialog box, click
“Appearance”>“Import”>“Files”




it will display the following windows, then double click ”



am.co.za.ico”

Press the left mouse button and drag ”cutterpro.cutterpor”




to the toolbar

Click **“OK”**


How to use:

Output the Designed file then click




“Plotter Origin” select **“Bottom left”**

“Plotter units:” select “1016”



Click “OK”



Select the port connected to the plotter and start.

